



# BTL Engineering Services, Inc.

5802 N. Occident Street P.O. Box 15718 Tampa, Florida 33684  
(813) 884-0755 - Hillsborough (727) 733-9347 - Pinellas (727) 846-1703 - Pasco (813) 886-5377 - Fax

July 25, 2016

Pasco County Planning & Growth Management  
8731 Citizens Dr.  
New Port Richey, FL 34654  
Phone: (727) 847-8193

Re: Geotechnical Review of Civil Drawings  
Proposed Hunters Ridge Multi-Family Townhome Buildings  
Rancho Del Rio Drive  
New Port Richey, Florida  
Pasco County ID: 11-26-16-0020-03300-0000  
BTL Job No. 5253-15-1934(C)

To Whom It May Concern:


*BTL Engineering Services, Inc.* has completed a geotechnical subsurface exploration at the referenced project site. The results of our subsurface exploration were presented in our geotechnical report, dated November 11, 2015.


Pursuant to Pasco County's requirement, *BTL Engineering Services, Inc.* has reviewed the civil drawings (General Notes, Sheet No. 4) prepared by Regency Design & Engineering, Inc. Based on our review of the above mentioned drawing sheet, it appears that the recommendations set forth in our geotechnical engineering report prepared for the project have been incorporated into the project plans and specifications and that the proposed project complies with the geotechnical report recommendations.

Should there be any questions regarding this letter, please do not hesitate to contact our office at (813) 884-0755.

Respectfully submitted,

**BTL ENGINEERING SERVICES, INC.**  
CA 2352

  
Mohammed A. Hai, P.E.  
Vice President  
FL Registration No. 59345



Geotechnical Engineering • Foundation Design • Forensic Foundation Engineering  
Materials Laboratory Testing • Construction Testing Services • Sinkhole Investigation